

Equipment History Report

This report provides history for a specific piece of tagged equipment, showing information on equipment properties, lifecycle states (purchase, in stores, service installation locations, multiple repairs, & scrap), and lifetime repair costs.



- Equipment Properties A table of properties associated with the equipment, such as Serial Number, Manufacturer, etc
- Days Installed vs Equipment Installation Number - A chart showing the number of days for each install
- **3.** History A table with details for each installation, including *Start Date*, *End Date*, *Number of Days*, *Type* (*Install, Repair, Scrap*), and *Remarks*.
- **4.** Equipment Repair Cost History A chart showing cost for each repair.



Equipment Properties Table & Days Installed Graph



Property	Value		
Frame Size	447TZ		
Model Number	7777		
Motor Mfg	Reliance		
Plant Tag	341		
Power	250 HP		
Serial Number	1MA473443-G2-SB		
Speed	1800 RPM		
Voltage - Stator	460 V		
Bars - Rotor (cnt)	0 PREHEAT FURNACE FAN		
Comments			
Connection Config (Stator)	Unknown		
Current - Full Load (Stator)	0 A		
Insulation Class	Unknown		
Motor Enclosure	ODP		
Nema Design Code	В		
Nema Power Code (AC)	Unknown		
Power Factor	0		
Service Factor	0		
Slots - Stator	0		

Equipment Properties (left) - A table of properties associated with the equipment, such as Serial Number, Manufacturer, etc

Days Installed vs Equipment Installation Number (below) - A chart showing the number of days for each install









History - A table with details for each installation, including *Start Date*, *End Date*, *Number of Days*, *Type (Install, Repair, Scrap)*, and *Remarks*.

	Start	End	Days	Туре	Remarks
\odot	Jan 01, 1984	Dec 15, 1987	1444	Install (1)	Removal: RUNNING THIS DATE REMOVED FOR NDT
~	Dec 15, 1987	Jan 28, 1988	44	Repair (1)	Send: REWIND CLASS F - BRGS
~	Feb 10, 1988	May 15, 1993	1921	Install (2)	Removal: GROUNDED
~	May 15, 1993	May 16, 1993	া	Repair (2)	Send: CHECK AND SCRAP
*	Jan 20, 2000		(6916)	Scrap	
~	Jan 20, 2000		(6916)	Scrap (3)	

Clicking the vill reveal additional information about the event. This may include *Installation Information, Removal Information, Repair Findings*, and more.



Locating the Report







