


Location History



This report provides a historical listing of tagged equipment installed at a component location, including access to design properties for each tagged equipment.

The chart shows the number of days for each install

The table displays the same data, along with a column for Remarks

Clicking the **▼** symbol at the left will reveal two more items, a *Properties* table and *Historical Location Data*

Properties Table and Historical Location

| Property | Value |
|------------------------------|---------------------|
| Frame Size | 447TZ |
| Model Number | ???? |
| Motor Mfg | Reliance |
| Plant Tag | 341 |
| Power | 250 HP |
| Serial Number | 1MA473443-G2-SB |
| Speed | 1800 RPM |
| Voltage - Stator | 460 V |
| Bars - Rotor (cnt) | 0 |
| Comments | PREHEAT FURNACE FAN |
| Connection Config (Stator) | Unknown |
| Current - Full Load (Stator) | 0 A |
| Insulation Class | Unknown |
| Motor Enclosure | ODP |
| Nema Design Code | B |
| Nema Power Code (AC) | Unknown |
| Power Factor | 0 |
| Service Factor | 0 |
| Slots - Stator | 0 |

The *Properties* table includes a complete list of properties associated with the equipment

The *Historical Location* tab may include *Installation Information*, *Removal Information*, *Repair Findings*, and more.

Historical Location

Location: 011 Ingot Plant > PREH > 69 > 2REC

Installation Information

Install Date:

Installation Work Order:

Installation Remarks:

Removal Information

Removal Date:

Removal Work Order:

Removal Remarks:

Repair Findings (based on the repair following this installation)

| Fault Type | Fault Group | Status | Level | Comment |
|---------------------------|--------------|----------------|-----------------|---------|
| Grounded | Stator Field | Unacknowledged | Secondary Cause | |
| Vibration/Bearings by NDT | Mechanical | Unacknowledged | Secondary Cause | |

Locating the Report

Asset Tree

- Reliable Manufacturing, Inc.
 - 101 Cooling Tower
 - Tower
 - CLDWELL
 - MOTOR1[1452/5282414005]
 - MOTOR2[56/1-5117-65842-01-1]
 - MOTOR3[1449/5282414001]

- Services**
- All Faults Summary
 - Asset Health Report
 - Condition Assessment Task Metrics
 - Condition Comments
 - Condition Entries by Date Range
 - Condition Entry Cost Tracking
 - Condition Risk Factor Rating Report
 - Condition Summary for Export
 - Condition Summary for Export - No Faults
 - Database Condition Assessment Metrics
 - Database Condition Assessment Metrics By Task
 - Green Comments
 - Locations Not Measured
 - Mean Time Between Failure
 - Open Condition Entries With Work Orders Assigned
 - Open Condition Entries Without Work Orders Assigned
 - Primary Failure Summary
 - Tango Browser Sanity Check
 - Work Planners Report
 - Plant Level Reports
 - Process Parameters
 - Condition Assessment Services

- Location Details
- Condition Entry Reports
 - Condition Case Details
 - Location History
- Location Actions
 - Add Planned Removal Status Entry
- Condition Management Actions
- Equipment Actions
- Equipment Reports
 - Equipment History
- Other Reports
 - Add Root Cause Entry
 - Condition Assessment History Report
 - Condition Assessment Severity Over Time
 - Equipment Traveler
 - Last Two Condition Assessments
 - Task Items Not Measured In Date Range

Available From Asset Tree Menu Under:

| | |
|---|---|
| <input checked="" type="checkbox"/> Plant | <input checked="" type="checkbox"/> Process Parameters |
| <input checked="" type="checkbox"/> Unit | <input checked="" type="checkbox"/> Condition Assessment Services |
| <input checked="" type="checkbox"/> Function | |
| <input checked="" type="checkbox"/> Asset | |
| <input checked="" type="checkbox"/> Component | |
| <input checked="" type="checkbox"/> Services | |