

## Work Planners Report



- 1 You may choose a Target Repair Date for the report. The default is today's date.
- 2You may also filter the list using keywords from field.

The table lists details of due inspections (see next page)

This report shows locations with installed or spares equipment due\* for inspection or rotation out of its current location by a specified date

\*Only applicable for equipment with defined maximum installation or storage intervals, such as safety relief valves.

	THEEL KENDDE IV	lanufacturing,	IIIC.									
▲ R	eport Options											
1   1	Target Repair Da	te: Jan 2	3, 2019	Run Re	port							
								2	2 Filter:			
			4	Equipment State	Last Inspection	Interval	Install Date	Unit	Function	Asset		
	Work Deadline	Work Action	Plant Tag	Equipment state	Last maperenan	III COI VOI	miscum bucc	o.iii	Turicuon	rusuce	Asset Con	
4-	Work Deadline Jun 02, 2009	Work Action Reinspect	V2000	Installed	Sep 06, 2006	1000	Sep 06, 2006	Safety Relief Valve Test		System 1	Asset Con Valve B	
4-			-	20.000					Area 1	System 1		
	Jun 02, 2009	Reinspect	V2000	Installed	Sep 06, 2006	1000		Safety Relief Valve Test	Area 1 Valve Storage	System 1	Valve B Bin 1-1	



## Work Planners Report



- Work Deadline
- Work Action (example: Reinspect)
- 3. Plant Tag
- Equipment State (Installed, In Spares)
- 5. Last Inspection (date of last inspection,
  - repair, or purchase order)

- 5
- 6

8 - 11.

Actions

**Install Date** 

Unit, Function, Asset, Component

Interval - Scheduled days between Work


- 10
- 11

	Work Deadline	Work Action	Plant Tag	Equipment State	Last Inspection	Interval	Install Date	Unit	Function	Asset	Asset Comp
4-	Jun 02, 2009	Reinspect	V2000	Installed	Sep 06, 2006	1000	Sep 06, 2006	Safety Relief Valve Test	Area 1	System 1	Valve B
4-	May 30, 2011	Reinspect	V1001	In Spares	Sep 02, 2008	1000		Safety Relief Valve Test	Valve Storage	Rack 1	Bin 1-1
4-	Jun 14, 2011	Reinspect	V1000	Installed	Sep 02, 2008	1000	Sep 17, 2008	Safety Relief Valve Test	Area 1	System 1	Valve D
4 -	Aug 02, 2011	Reinspect	V1002	Installed	Oct 15, 2008	1000	Nov 05, 2008	Safety Relief Valve Test	Area 1	System 1	Valve A



## Locating the Report





▼ Condition Assessment Services

